

ANNUAL SURVEYS.

9762
JH

No. 337 Survey held at London Date May 23 1843
on the "Charles" Master Dallin
Tonnage 334 Built at Whitby When built 1815
By whom built — Owners Douglas 27
Port belonging to London Destined Voyage West India
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1227, 2466 Port of London Classed A.1

The Surveyor is required to state the present Condition of the 3718, 5202, 5786, 6423, 6933, 7034, 7916, 9230,

Decks <u>plaid & worn</u>	Transoms <u>good when seen</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do do</u>	Pumps <u>good & sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do do</u>	Masts, Yards, &c. <u>do do</u>
Spirketting <u>good</u>	Wales <u>do</u>	Sails <u>do do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>—</u>

General Observations and Opinion,
as required by the Instructions, The decks are worn and much plaid but light
The general appearance is fairly efficient for the
conveyance of dry and perishable Cargoes may remain
as classed
Committee Minute 26th May 1843
Character assigned A.1

No. 53 Survey held at London Date May 16 19 23 1843
on the "Reumseh" Master Gardiner
Tonnage 451 Built at Canada When built 1840
By whom built — Owners Glass
Port belonging to Brunswick Destined Voyage India
If Surveyed Afloat or in Dry Dock West India & Fitchers Sh

Original Survey, No. 999 Port of Clyde Classed 5 A1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>good & sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do do</u>
Spirketting <u>good</u>	Wales <u>do</u>	Sails <u>do do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u>

General Observations and Opinion,
as required by the Instructions, Is a remarkably well built vessel of that
sort and appears every where sound and good now fitted
in the openings between the timbers with salt may
Committee Minute 26th May 1843
Character assigned 5 A1