

ANNUAL SURVEYS.

9/83

No. 600 Survey held at London Date May 31st 1843
 on the Bk. Mary Ann Master A. P. Turner
 Tonnage 225 Built at Peterhead When built 1837
 By whom built _____ Owners Turner & Co
 Port belonging to Peterhead Destined Voyage C. G. Hope
 If Surveyed Afloat or in Dry Dock on the Mays

Original Survey, No. 7395 Port of London 1841 Classed GA 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & otherwise</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Not found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>Good</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Yellow Metal good</u>

General Observations and Opinion, At the present time Masts & upper works called
 as required by the Instructions, is in a very efficient state to continue in her
present shape

Committee Minute 9th June 1843

Character assigned GA 1

No. 166 Survey held at London Date May 31st 1843
 on the Bk. Whamoa Master J. Hattis
 Tonnage 340 Built at Sunderland When built 1841
 By whom built _____ Owners Hattis & Co
 Port belonging to London Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 4838 Port of Singapore Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Not found</u>
Plank Shears <u>"</u>	Counter <u>Good</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Yellow Metal good</u>

General Observations and Opinion, is in a very efficient state & appears in all
 as required by the Instructions, respects eligible to retain her present shape

Committee Minute 9th June 1843

Character assigned 10 A 1

