

ANNUAL SURVEYS.

9789

No. 254 Survey held at London Date 5th June 1843
 on the Ship "Catherine Green" Master R Dyott
 Tonnage 349 Built at Shields When built 1839
 By whom built Owners B Green
 Port belonging to London Destined Voyage St Kitts
 If Surveyed Afloat or in Dry Dock Kings Dock & West India Dock

Original Survey, No. 1168 Port of Newcastle, Lon. 1956, 9087, 9137. Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>New Main and 3 Fore Masts</u>
Spirketting	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Sufficient</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Yellow Metal fair</u>

General Observations and Opinion,
as required by the Instructions,

at this time the Yellow Metal has been largely patched. She has had a New Main & Fore Masts and being in efficient condition

Committee Minute 9th June 1843 May remain as Classed

Character assigned 10 A 1 Joseph H. Hatcher

No. 132 Survey held at London Date 7th June 1843
 on the Ship "Derwent" Master McPherson
 Tonnage 362 Built at Sunderland When built 1835
 By whom built Owners Heish Ho
 Port belonging to London Destined Voyage Robert Town
 If Surveyed Afloat or in Dry Dock Hatchers Dock

Original Survey, No. 277 Port of Sunderland, Lon 5393, 6507, 8894. Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirketting	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>New June 1843</u>

General Observations and Opinion,
as required by the Instructions,

at this time she was stripped and her bottom was Caulked and recoppered on tarred paper as she is in efficient

Committee Minute 9th June 1843 Condition she may remain as

Character assigned 11 A 1 Classed Joseph H. Hatcher