

ANNUAL SURVEYS.

9191

No. 5 Survey held at London Date 24 May 1843
 on the Ship "Malabar" Master Pollock
 Tonnage 647 Built at London When built 1834
 By whom built Green Wigram & Co Owners R Green
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Green Dock

Original Survey, No. 461, 1704, Port of London
6347, 6914, 8741

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Yellow Metal May 1843</u>

General Observations and Opinion,
 as required by the Instructions,

at this time her bottom was stripped, Caulked
 and Sheathed with Yellow Metal and as

Committee Minute 9th June 1843 as Claped
 Character assigned 12 A 1 Joseph H. Ritchie
rec'd 4th

No. 60 Survey held at London Date 30th May 1843
 on the Ship Maidstone Master Nash
 Tonnage 816 Built at London When built 1839
 By whom built Green Wigram & Co Owners Wigram
 Port belonging to London Destined Voyage India Calcutta
 If Surveyed Afloat or in Dry Dock Wigram Dock

Original Survey, No. 5456, 6449, Port of London
7625, 8834

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Yellow Metal May 1843</u>

General Observations and Opinion,
 as required by the Instructions,

at this time the ship was stripped her
 bottom, topsides & deck Caulked and bottom
 Sheathed with Yellow Metal and she

Committee Minute 9th June 1843 is in efficient Condition May
 Character assigned 12 A 1 as Claped
rec'd 4th Joseph H. Ritchie