

ANNUAL SURVEYS.

9807

No. *500* Survey held at *London* Date *27 May* 184*3*
 on the *By Gibraltar* Master *Forman*
 Tonnage *267* Built at *Sunderland* When built *1842*
 By whom built *—* Owners *Forman*
 Port belonging to *London* Destined Voyage *Dominica*
 If Surveyed Afloat or in Dry Dock *Afloat*

Original Survey, No. *2250* Port of *Sunderland* Classed *7 A 1*

The Surveyor is required to state the present Condition of the

Decks <i>Good</i>	Transoms <i>Good</i>	Capstan <i>—</i>
Upper Deck Beams & Fastenings <i>firm</i>	Timbers of the Frame <i>do</i>	Pumps <i>Sufficient Good</i>
Lower Deck Beams & Fastenings <i>do</i>	Topsides <i>do</i>	Masts, Yards, &c. <i>do</i> <i>do</i>
Spirkettling <i>Good</i>	Wales <i>do</i>	Sails <i>do</i> <i>do</i>
Plank Shears <i>do</i>	Counter <i>do</i>	Cables <i>do</i> <i>do</i>
Waterways <i>do</i>	Plank and Treenails <i>do</i> (Outside to the Water's Edge.)	Anchors No. of <i>do</i> <i>do</i>
Hatchway Comings <i>do</i>	Rudder <i>do</i>	Standing & Running Rigging <i>do</i> <i>do</i>
Breasthooks <i>do</i>	Windlass <i>do</i>	Copper <i>do</i> <i>1842</i>

General Observations and Opinion,

as required by the Instructions,

*Is in an efficient condition and may
 be considered as Classed* *Houtman*

Committee Minute *13th June* 184*3*

Character assigned *7 A 1*

No. *500* Survey held at *London* Date *5 June* 184*3*
 on the *St. "Leo"* Master *Stire*
 Tonnage *217* Built at *Jersey* When built *1835*
 By whom built *—* Owners *Richard*
 Port belonging to *Jersey* Destined Voyage *Petersburg*
 If Surveyed Afloat or in Dry Dock *Afloat*

Original Survey, No. *1* Port of *Jersey, St. 30/7* Classed *8 A 1*

The Surveyor is required to state the present Condition of the

Decks <i>Good</i>	Transoms <i>Good</i>	Capstan <i>—</i>
Upper Deck Beams & Fastenings <i>firm</i>	Timbers of the Frame <i>Good when the</i>	Pumps <i>Sufficient Good</i>
Lower Deck Beams & Fastenings <i>do</i>	Topsides <i>Good</i>	Masts, Yards, &c. <i>do</i> <i>do</i>
Spirkettling <i>Good</i>	Wales <i>do</i>	Sails <i>do</i> <i>do</i>
Plank Shears <i>do</i>	Counter <i>do</i>	Cables <i>do</i> <i>do</i>
Waterways <i>do</i>	Plank and Treenails <i>do</i> (Outside to the Water's Edge.)	Anchors No. of <i>2 Bows 1 Stern 1 Kedge</i>
Hatchway Comings <i>do</i>	Rudder <i>do</i>	Standing & Running Rigging <i>Good</i>
Breasthooks <i>do</i>	Windlass <i>do</i>	Coppered <i>Stated to be 3 1/2 years since</i>

General Observations and Opinion,

as required by the Instructions,

*appears in good condition in every respect
 part and may be continued as Classed* *Houtman*

Committee Minute *13th June* 184*3*

Character assigned *8 A 1*



© 2019

Lloyd's Register
 Foundation