

# ANNUAL SURVEYS.

9827

No. 279 Survey held at L. M. W. W. Date 10 June 1843  
 on the Sh. Manna Monarch Master Fragin  
 Tonnage 576 Built at London When built 1838  
 By whom built - Owners J. B. L.  
 Port belonging to London Destined Voyage India  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 6433, 7660 Port of London

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u>-</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u>good</u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions,

Is in the most efficient condition for for the  
conveyance of any perishable cargo to & from all parts of  
the world and may remain as long

Committee Minute 20th June 1843

Character assigned A. 1 Steeple

No. 70 Survey held at London Date 10 June 1843  
 on the Sh. Manna Venus Master Morfe  
 Tonnage 232 Built at London When built 1821  
 By whom built - Owners G. & T. Co.  
 Port belonging to London Destined Voyage -  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 7262 Port of London

Classed A. 1 expansive

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good</u>	Capstan <u>-</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do when seen</u>	Pumps <u>Sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>good</u>	Masts, Yards, &c. <u>good</u>
Spirkettling <u>good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u>-</u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions,

Is in an efficient condition for for the  
conveyance of any perishable cargo and may remain  
as long as the water's edge

Committee Minute 20th June 1843

Character assigned A. 1 Steeple



© 2019

Lloyd's Register  
Foundation

LON 615-0279