

REPORT of SURVEY for REPAIRS.

Change of owner 9844

No. 2 Survey held at London Date 1st May 184 3
 on the M Fairlie Master Burns
 Tonnage 756 Built at Calcutta When built 1812
 By whom built — Owners Somers
 Port belonging to London Destined Voyage Transport
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2642, 4486, Dated 6083, 7634, 9453,
 Port London Classified * F. 1

REPAIRS

*Keel
 Docked bottom examined run up & for piece of false
 yellow metal upaired*

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *Decks Coaked is in the most efficient
 condition for the conveyance of dry and perishable
 cargo to and from all parts of the World and may be
 continued as classed*

The Amount of Fee.....£ 3 : — : — is received by me, *AS*

Committee's Minute 30th June 1843

Character assigned A 1

© 2019

Lloyd's Register
 Foundation

LONG15 - 0298