

ANNUAL SURVEYS.

9862

No. 436 Survey held at London Date June 20th 1843
 on the Bk. Tuscar Master Rabson
 Tonnage 181 Built at Poole When built 1831
 By whom built _____ Owners Bartholomew & Son
 Port belonging to London Destined Voyage Liverpool & China
 If Surveyed Afloat or in Dry Dock Gun Dock

Original Survey, No. 1169, 3515, 4592, 8701 Port of London Cont 1842 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Not seen</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>See</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Overhauling</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Efficient</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>2</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>As before</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>good smooth</u>

General Observations and Opinion, as required by the Instructions, A pair of Iron knees put to secure the Bulk of the Deck
She is in an efficient state & in my opinion eligible
to remain as classed 12 A 1

Committee Minute 14th July 1843

Character assigned Cont 12 A 1

George Bayley

No. _____ Survey held at _____ Date _____ 184 _____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. _____
Spirkettling _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper _____

General Observations and Opinion, as required by the Instructions,

Committee Minute _____ 184 _____

Character assigned _____



© 2019

Lloyd's Register Foundation

LON 615-0317