

ANNUAL SURVEYS.

9880

No. 112 Survey held at London Date 12th June 1843
 on the Brig "Orator" Master Terry
 Tonnage 321 Built at Sunderland When built 1835
 By whom built _____ Owners S. Allan
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock in Limekiln Slip

Original Survey, No. 365 Port of Sunderland, Lon. 219 1/4, 22 1/4 Classed 11 A 1
3551, 6000, 1805

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>3 Bows 11 1/2 Kgs</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Sufficient</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Good</u>

General Observations and Opinion,
 as required by the Instructions,

This vessel is in good and efficient Condition
and may remain as Classed
Joseph H. Ritchie

Committee Minute 14th July 1843

Character assigned 11 A 1

No. 360 Survey held at London Date 16th June 1843
 on the Brig "Duke of Richmond" Master D. Clark
 Tonnage 421 Built at Dystart When built 1842
 By whom built _____ Owners R. Leslie
 Port belonging to Dundee Destined Voyage Robert Town
 If Surveyed Afloat or in Dry Dock in Limekiln Slip

Original Survey, No. 944 Port of Leith Classed 9 A 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Do</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Good</u>

General Observations and Opinion,
 as required by the Instructions,

This vessel is in good and efficient
Condition and may remain as Classed
Joseph H. Ritchie

Committee Minute 14th July 1843

Character assigned 9 A 1