

REPORT of SURVEY for REPAIRS.

No. 59 Survey held at London Date July 10 towards 1843
 on the Ship Canina Master Canney
 Tonnage 383 Built at Newcastle When built 1829
 By whom built John Smith Owners Burton & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 8008, 8007 Dated July 1843 Classed Antennae A 1
12 A 1
4 years 1841
 Port London

REPAIRS

As the present time shippers - all the Ironails driven out from the water down to the Bilge - Hugs - Caulked keel up & sheathed with yellow metal - and generally overhauled

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Pumps <u>Good</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Masts, Yards, &c. <u>Good efficient</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>See See</u>
Waterways <u>"</u>	Plank & Treenails (Outside to the Water's Edge) <u>"</u>	Cables <u>See See</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of <u>3. 1. 2</u>
Breasthooks <u>"</u>	Copper <u>Y M 1843</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion, It is stated that this vessel was ashore about 2 years since which accounts for the broken and strained state of the Ironails - She is now in a good and efficient state of repair and eligible in an opinion to remain as classed A 1

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute 25th July 1843

Character assigned Ant? 4 A 1