

# ANNUAL SURVEYS.

9923

No. 329 Survey held at London Date 7<sup>th</sup> July 1843  
 on the Sch. "Cowan Hill" Master Wright  
 Tonnage 91 old Built at Dumbarton When built 1839  
 By whom built Wright & Co. Owners Wright & Co.  
 Port belonging to Glasgow Destined Voyage Fernies Ways  
 If Surveyed Afloat or in Dry Dock Fernies Ways

Original Survey, No. 658 Port of Clyde, 4769 Liverpool Classed 8-A-1

The Surveyor is required to state the present Condition of the

|   |                                      |  |
|---|--------------------------------------|--|
| Decks <u>Good</u>                       | Transoms <u>Good</u>                 | Capstan <u>Good</u>                      |
| Upper Deck Beams & Fastenings <u>Do</u> | Timbers of the Frame <u>Not Seen</u> | Pumps <u>Good</u>                        |
| Lower Deck Beams & Fastenings <u>Do</u> | Topsides <u>Good</u>                 | Masts, Yards, &c. <u>Sufficient</u>      |
| Spirketting <u>Do</u>                   | Wales <u>Do</u>                      | Sails <u>Settle</u>                      |
| Plank Shears <u>Do</u>                  | Counter <u>Do</u>                    | Cables <u>Settle</u>                     |
| Waterways <u>Do</u>                     | Plank and Treenails <u>Do</u>        | Anchors No. of <u>Settle</u>             |
| Hatchway Comings <u>Do</u>              | (Outside to the Water's Edge.)       | Standing & Running Rigging <u>Settle</u> |
| Breasthooks <u>Do</u>                   | Rudder <u>Do</u>                     | Copper <u>Single bottom</u>              |
|   | Windlass <u>Do</u>                   |  |

General Observations and Opinion,  
as required by the Instructions,

*At this time her bottom was beamed & grained  
and as she appears in efficient condition  
May remain as Classed*

Committee Minute 20<sup>th</sup> July 1843

Character assigned S. A. 1

*Joseph H. Hatcher*

No. 13 Survey held at London Date 13 July 1843  
 on the Brig "Terra Nova" Master Setliger  
 Tonnage 89 Built at Greenock When built 1841  
 By whom built Symonds & Co. Owners Stewart & Parny  
 Port belonging to Greenock Destined Voyage New found land  
 If Surveyed Afloat or in Dry Dock on Fernies Ways

Original Survey, No. 1074 Port of Clyde Classed 10-A-1

The Surveyor is required to state the present Condition of the

|   |                                      |   |
|---|--------------------------------------|---|
| Decks <u>Good</u>                           | Transoms <u>Good</u>                 | Capstan <u>Good</u>                       |
| Upper Deck Beams & Fastenings <u>Settle</u> | Timbers of the Frame <u>Not Seen</u> | Pumps <u>Settle</u>                       |
| Lower Deck Beams & Fastenings <u>Settle</u> | Topsides <u>Good</u>                 | Masts, Yards, &c. <u>Sufficient</u>       |
| Spirketting <u>Settle</u>                   | Wales <u>Settle</u>                  | Sails <u>Settle</u>                       |
| Plank Shears <u>Settle</u>                  | Counter <u>Settle</u>                | Cables <u>Settle</u>                      |
| Waterways <u>Settle</u>                     | Plank and Treenails <u>Settle</u>    | Anchors No. of <u>3/13 1st &amp; 1/16</u> |
| Hatchway Comings <u>Settle</u>              | (Outside to the Water's Edge.)       | Standing & Running Rigging <u>Good</u>    |
| Breasthooks <u>Settle</u>                   | Rudder <u>Settle</u>                 | Copper <u>atched Good</u>                 |
|   | Windlass <u>Settle</u>               |   |

General Observations and Opinion,  
as required by the Instructions,

*at this time she was laid on the ground  
to inspect the state of the Copper which was  
in fair condition and was patched she  
is in efficient condition and*

Committee Minute 28<sup>th</sup> July 1843

Character assigned 10-A-1

*May remain as Classed*  
*Joseph H. Hatcher*