

ANNUAL SURVEYS.

9930

No. 52 Survey held at London Date July 29 1843
 on the Bk Conservative Master Prosen
 Tonnage 345 Built at Sunderland When built 1840
 By whom built _____ Owners Greene & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1791 Port of Sunderland, Lon 6957, 8062, 8070 Classed 10A1
 & 9084

The Surveyor is required to state the present Condition of the

| | | |
|--|---|--|
| Decks <u>Good</u> | Transoms <u>Sound</u> | Capstan <u>Good</u> |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame <u>"</u> | Pumps <u>"</u> |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>Good</u> | Masts, Yards, &c. <u>"</u> |
| Spirkettling <u>Good</u> | Wales <u>"</u> | Sails <u>Wet & sound</u> |
| Plank Shears <u>"</u> | Counter <u>"</u> | Cables <u>"</u> |
| Waterways <u>"</u> | Plank and Treenails <u>Good</u> (Outside to the Water's Edge.) | Anchors No. of <u>"</u> |
| Hatchway Comings <u>"</u> | Rudder <u>"</u> | Standing & Running Rigging <u>Good</u> |
| Breasthooks <u>"</u> | Windlass <u>"</u> | Copper <u>"</u> |

General Observations and Opinion, Caulked from the upper to the Waterway seam is
 as required by the Instructions, quite last and is throughout in a very high state
of efficiency to continue in her present class

Committee Minute 1st August 1843
 Character assigned 10 A1

W. Woodson

No. 33 Survey held at London Date July 26 1843
 on the Bk Achilles Master C. Pirouet
 Tonnage 200 Built at Jersey When built 1841
 By whom built _____ Owners Pellier
 Port belonging to Jersey Destined Voyage _____
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 229 Port of Jersey, Lon 8873 Classed 9A1

The Surveyor is required to state the present Condition of the

| | | |
|--|--|----------------------------------|
| Decks <u>Good</u> | Transoms <u>Sound</u> | Capstan _____ |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame <u>"</u> | Pumps _____ |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>Good</u> | Masts, Yards, &c. _____ |
| Spirkettling <u>Good</u> | Wales <u>"</u> | Sails <u>Good</u> |
| Plank Shears <u>"</u> | Counter <u>"</u> | Cables _____ |
| Waterways <u>"</u> | Plank and Treenails <u>"</u> (Outside to the Water's Edge.) | Anchors No. of <u>Sufficient</u> |
| Hatchway Comings <u>"</u> | Rudder <u>"</u> | Standing & Running Rigging _____ |
| Breasthooks <u>"</u> | Windlass <u>"</u> | Copper _____ |

General Observations and Opinion, Is in a very good & efficient state & may
 as required by the Instructions, continue as classed

Committee Minute 1st August 1843
 Character assigned 9 A1

W. Woodson



© 2019

Lloyd's Register
Foundation