

# ANNUAL SURVEYS.

9965

No. 433 Survey held at London Date Aug 11 1843  
 on the Ship Windsor Master Vop?  
 Tonnage 650 Built at Blackwall When built 1835  
 By whom built Green & Green Owners R Green  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Green Dock Blackwall

Original Survey, No. 14098, 51444 Port of London August 1842 Classed 12A1  
6517, 7693, 9171,


The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>Good &amp; efficient</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Caulked</u>	Masts, Yards, &c. <u>So &amp; so</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Overhauling</u>
Plank Shears <u>"</u>	Counter <u>Good</u>	Cables <u>As before; good</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Efficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Up - smooth &amp; good</u>

General Observations and Opinion, But water reboiled - Ym repaired - Masts & Topsides  
 as required by the Instructions, caulked - In my opinion she is eligible to  
remain as classed 12A1

Committee Minute 18th August 1843  
 Character assigned 12A1

*George Bayley*



Lloyd's Register  
Foundation

5270-0425