

REPORT of SURVEY for REPAIRS.

Change of Owners re 18001

No. 134 Survey held at London Date 18th April 1843
 on the Mk Margaret Master H. Cross
 Tonnage 312 Built Timber When built 1829
 By whom built _____ Owners W. Dowell King Lane Street
 Port belonging to London Destined Voyage New Castle
 If Surveyed Afloat or in Dry Dock Afloat Long Dock

Original Survey, No. 2123, 29/6 Dated _____

Classed expunged
 S.S. 38 3 1/2

Port Liverpool, Lon 6307

REPAIRS

at the present time planks in the quarter replaced.

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, has Docked, Copper shipped the planks of the
topsides on each quarter were removed and the timbers, beam
ends, knees, & clamps were found decayed as far as the was
opened. She has since sold and in my opinion not sufficiently
upaired to enable her to any class -

The Amount of Fee £ : : is received by me,

Committee's Minute 23th August 1843

Character assigned Expunged



© 2019

Lloyd's Register
 Foundation

LON615-0463