

REPORT of SURVEY for REPAIRS.

10,007

No. 120 Survey held at London Date Aug 12 1843
 on the Br. Castle Lachlan Master Bruce
 Tonnage 435 Built at Greenock When built 1811
 By whom built _____ Owners Dawson & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Curling Dry Dock

Original Survey, No. 612.1752 Dated 1842 Classed *E.1
 Port London 3708, 4317, 4643, 5513, 5624, 5755, 6624, 6961, 81987.
 REPAIRS New lower deck shelves refitted to pair long Riders
4 Deck Stanchions 2 pointers & crutches 2 knees
on Counter Transom Shifted upper part of Steer Post
Sculked from copper up

The Timbers exposed are good & efficient

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good & efficient *Good & efficient* *Good* *do* *do & efficient* *Rehauled* *Good & efficient* *3-1-2* *Good*

General Observations and Opinion.

*In my opinion she is eligible for the conveyance of dry and perishable cargoes to and from all parts of the world & is fit to be continued as classed *E.1*

Wm. M. M. M.

The Amount of Fee.....£ 2 : - : - is received by me, *Wm. M. M. M.*

Committee's Minute 1st September 1843

Character assigned E.1 asterisk

Special 21.1.0

Record repair



© 2019

Lloyd's Register Foundation

LONG 15-0469