

ANNUAL SURVEYS.

10,019

No. ³⁷³ ~~487~~ Survey held at London Date 27 July 1843
 on the Chr Port Fluswood Master Vindler
 Tonnage 180 Built at Aberdeen When built 1840
 By whom built Mr Owners Knights
 Port belonging to Fluswood Destined Voyage Cape of H
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 686 Port of Aberdeen, Sin 1877 Classed 12 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>No</u>	Pumps <u>Sufficient Good</u>
Lower Deck Beams & Fastenings <u>No</u>	Topsides <u>No</u>	Masts, Yards, &c. <u>No</u> <u>No</u>
Spirketting <u>Good</u>	Wales <u>No</u>	Sails <u>No</u> <u>No</u>
Plank Shears <u>No</u>	Counter <u>No</u>	Cables <u>No</u> <u>No</u>
Waterways <u>No</u>	Plank and Treenails <u>No</u> (Outside to the Water's Edge.)	Anchors No. of <u>No</u> <u>No</u>
Hatchway Comings <u>No</u>	Rudder <u>No</u>	Standing & Running Rigging <u>No</u> <u>No</u>
Breasthooks <u>No</u>	Windlass <u>No</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

is Classed

is in an efficient condition and may remain
Portingway

Committee Minute 5th September 1843

Character assigned 12 A1

No. ⁴⁸⁸ ~~487~~ Survey held at London Date 28 Aug 1843
 on the Mk Mary Master Hickinson
 Tonnage 266 Built at Chatham When built 1809
 By whom built — Owners Hill
 Port belonging to London Destined Voyage South Seas
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1860, 2206, 2306 Port of London Classed A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>Keelson</u>	Pumps <u>Sufficient Good</u>
Lower Deck Beams & Fastenings <u>No</u>	Topsides <u>,</u>	Masts, Yards, &c. <u>No</u> <u>No</u>
Spirketting <u>Good</u>	Wales <u>,</u>	Sails <u>No</u> <u>No</u>
Plank Shears <u>No</u>	Counter <u>,</u>	Cables <u>No</u> <u>No</u>
Waterways <u>No</u>	Plank and Treenails <u>,</u> (Outside to the Water's Edge.)	Anchors No. of <u>No</u> <u>No</u>
Hatchway Comings <u>No</u>	Rudder <u>,</u>	Standing & Running Rigging <u>No</u> <u>No</u>
Breasthooks <u>No</u>	Windlass <u>,</u>	Copper <u>Good New 1843</u>

General Observations and Opinion,

as required by the Instructions,

has not been at sea since last Surveyed now
fitted and about to sail is in efficient condition and may
remain as Classed.

Committee Minute 5th September 1843

Character assigned A1

