

# ANNUAL SURVEYS.

10,159

No. 433 Survey held at London Date Oct 20<sup>th</sup> 1843  
 on the Bk. Anna Master Simpson  
 Tonnage 311 Built at Yarmouth When built 1825  
 By whom built          Owners Buckford  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 9175 Port of London 1838 Rebuilt          Classed 7A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>        </u>
Upper Deck Beams & Fastenings <u>        </u>	Timbers of the Frame <u>Sound</u>	Pumps <u>        </u>
Lower Deck Beams & Fastenings <u>        </u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>        </u>
Spirketting <u>Good</u>	Wales <u>        </u>	Sails <u>Good</u>
Plank Shears <u>        </u>	Counter <u>        </u>	Cables <u>        </u>
Waterways <u>        </u>	Plank and Treenails <u>        </u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>        </u>	Rudder <u>        </u>	Standing & Running Rigging <u>        </u>
Breasthooks <u>        </u>	Windlass <u>        </u>	Copper <u>on 1844</u>

General Observations and Opinion, This vessel is in a very good & efficient state  
 as required by the Instructions, and in every respect fit to retain her present  
Place

Committee Minute 24<sup>th</sup> October 1843

Character assigned Reit 7 A1

No. 433 Survey held at London Date Oct 20<sup>th</sup> 1843  
 on the Bk. John Blake Master Whiteway  
 Tonnage 216 Built at Teignmouth When built 1830  
 By whom built          Owners Blake & Co  
 Port belonging to Exeter Destined Voyage St Vincent  
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 7472 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>        </u>	Timbers of the Frame <u>Sound</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>        </u>	Topsides <u>        </u>	Masts, Yards, &c. <u>        </u>
Spirketting <u>        </u>	Wales <u>        </u>	Sails <u>Well found</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>        </u>
Waterways <u>        </u>	Plank and Treenails <u>        </u> (Outside to the Water's Edge.)	Anchors No. of <u>        </u>
Hatchway Comings <u>        </u>	Rudder <u>        </u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>        </u>	Windlass <u>        </u>	Copper <u>Yellow Metal 1844</u>

General Observations and Opinion, This vessel is in a very good & efficient condition  
 as required by the Instructions, to continue her present Place

Committee Minute 24<sup>th</sup> October 1843

Character assigned 12 A1



© 2019

Lloyd's Register  
Foundation

210-919207