

ANNUAL SURVEYS.

10,231

No. 22 Survey held at London Date 17th Oct 1843
 on the Sch. Agney Master White
 Tonnage 165 Built at Southampton When built 1839
 By whom built _____ Owners Captain & Co
 Port belonging to London Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock on West India Wharfs

Original Survey, No. 9206 Port of London

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Not Seen</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Do</u>	Timbers of the Frame <u>Not Seen</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>Do</u>	Wales <u>Do</u>	Sails <u>Suit</u> <u>Good</u>
Plank Shears <u>Do</u>	Counter <u>Do</u>	Cables <u>Do</u>
Waterways <u>Do</u>	Plank and Treennails <u>Do</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 B 1 H 2 K</u>
Hatchway Comings <u>Do</u>	Rudder <u>Do</u>	Standing & Running Rigging <u>Sufficient</u>
Breasthooks <u>Do</u>	Windlass <u>Do</u>	Copper <u>Patched</u> <u>Good</u>

General Observations and Opinion,
 as required by the Instructions,

at present she was laid a ground to inspect
 the State of the Copper, which was Patched
 she presented a firm & satisfactory appearance
 and in my opinion is in
 efficient condition & may remain
 as Classed 12 A 1

Committee Minute 17th November 1843

Character assigned 12 A 1

LON 616 - 0220