

# ANNUAL SURVEYS.

10,232

No. 406 Survey held at London Date 19 Oct. 1843  
on the Sch<sup>r</sup> Heroine Master Barrett  
Tonnage 141 Built at Guernsey When built 1841  
By whom built Guernsey Owners Robin & Co  
Port belonging to Guernsey Destined Voyage St Lucia  
If Surveyed Afloat or in Dry Dock On Hermsley's way

Original Survey, No. 268 Port of Guernsey Classed SA 1

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Not Seen</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Good</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Good</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>28 1st 11</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Good</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>	Copper	<u>Painted good</u>

General Observations and Opinion,  
as required by the Instructions,

At Present she was opened for government  
Survey and is in efficient Condition  
and may remain as Classed

Committee Minute 17th November 1843

Character assigned SA 1

Joseph H. Hilder

No. 241 Survey held at London Date 24 Oct. 1843  
on the Bark Black River Packet Master Baker  
Tonnage 265 Built at Southampton When built 1825  
By whom built London Owners Captain Goult X  
Port belonging to London Destined Voyage Blackwoods Dock  
If Surveyed Afloat or in Dry Dock in Blackwoods Dock

Original Survey, No. 242 Port of Plymouth Classed 10 A 1

Rest 43

The Surveyor is required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Capstan	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame	<u>Not Seen</u>	Pumps	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Topsides	<u>Good</u>	Masts, Yards, &c.	<u>Sufficient</u>
Spirkettling	<u>Do</u>	Wales	<u>Do</u>	Sails	<u>Do</u>
Plank Shears	<u>Do</u>	Counter	<u>Do</u>	Cables	<u>Do</u>
Waterways	<u>Do</u>	Plank and Treenails (Outside to the Water's Edge.)	<u>Do</u>	Anchors No. of	<u>Do</u>
Hatchway Comings	<u>Do</u>	Rudder	<u>Do</u>	Standing & Running Rigging	<u>Do</u>
Breasthooks	<u>Do</u>	Windlass	<u>Do</u>		<u>Yellow Metal new</u>

General Observations and Opinion,  
as required by the Instructions,

At Present she has been Caulked from  
the Keel to the Gunwale and the bottom  
sheathed with Yellow Metal on dry Paper  
she is in most efficient Condition

Committee Minute 17th November 1843

Character assigned SA 1

Joseph H. Hilder