

ANNUAL SURVEYS.

10,276

No. 14 Survey held at London Date Dec 5 1843
 on the By Gladwin Master R Jones
 Tonnage 158 Built at Bathampton When built 1824
 By whom built — Owners Griffiths
 Port belonging to London Destined Voyage Seyhorn
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 8262 Port of London

Classed A/1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>in wholeness</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>efficient</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good when new</u>

General Observations and Opinion,

as required by the Instructions,

The appears in good substantial condition
fit for the conveyance of dry and perishable Cargos
to and from all parts of the world, and may remain

Committee Minute 8th December 1843

Character assigned

A/1 Attain no classed Continued

No. 213 Survey held at London Date Dec 5 1843
 on the M Florence Master Davis
 Tonnage 179 Built at Garnmouth When built 1829
 By whom built — Owners Ried & Co
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 8894 Port of London

Classed 2 A/1
 Cont. 41 — 4 Yrs

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>efficient</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u>

General Observations and Opinion,


as required by the Instructions,

appears very sound and good and may
remain as classed

Committee Minute 8th December 1843

Character assigned

Class 4 A/1 Attain



© 2019

Lloyd's Register
Foundation

8270-0268