

# REPORT of SURVEY for REPAIRS.

*& Change of Owners*

No. 96 Survey held at Sunderland Date Nov 10 1843 Jan 7 1844  
 on the Bk Pathfinder Master J Bruton  
 Tonnage 316 Built at Sunderland When built 1841  
 By whom built \_\_\_\_\_ Owners Lewis & Co  
 Port belonging to Sunderland Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10,198 Classed P A 1

Port Sunderland

REPAIRS *Shipped, sheathing unnailed, listing cut off the hood ends & caulked also the wales & topsides caulked, five pair of standard knees on the hold beams upper belt through the deck clamps, and sheathed with yellow metal.*

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of <u>3 brass 1 Iron 1 Hedge</u>
Breasthooks		Standing & Running Rigging

General Observations and Opinion, *Is throughout in a very efficient state to return her present Class*

*Wm. H. M. Watson*

The Amount of Fee.....£ 2 :— :— is received by me, *Wm. H. M. Watson*

Committee's Minute 9th January 1844

Character assigned P A 1



© 2019

Lloyd's Register Foundation