

ANNUAL SURVEYS.

10.358

No. 81 Survey held at London Date Jan^y 13 1844
 on the Bk David Suckie Master Suckie
 Tonnage 320 Built at Sunderland When built 1837
 By whom built _____ Owners J Suckie
 Port belonging to London Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock Wate India Dock

Last
 Original Survey, No. 5825 Port of London

Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Is in all respects in a good & efficient state to remain
 as required by the Instructions, as classed has been in Dry Dock & had her bottom
examined

Committee Minute 23rd January 1844

Character assigned 10 A 1

Math. P. P. P.

No. 25 Survey held at London Date Jan^y 10 1844
 on the Bk Unicorn Master Mullens
 Tonnage 315 Built at Whitby When built 1834
 By whom built _____ Owners Mullens
 Port belonging to London Destined Voyage Spring
 If Surveyed Afloat or in Dry Dock Fletcher Dock

Last
 Original Survey, No. 9289 Port of London

Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Is in all respects in a good & efficient state to remain
 as required by the Instructions, as classed has been in Dry Dock & had her bottom
examined
Is throughout in a very efficient state retain her
present Class

Committee Minute 23rd January 1844

Character assigned 10 A 1

Math. P. P. P.
