

REPORT of SURVEY for REPAIRS.

10,362
11

Change of Property

No. 64 Survey held at London Date Feb 25th 1847
 on the Schooner Lady Leigh Master Wing
 Tonnage 109 Built at Newport Monmouth When built 1836
 By whom built _____ Owners ~~Robert~~ Fitzherbert
 Port belonging to Bristol Destined Voyage New Zealand
London
 If Surveyed Afloat or in Dry Dock Dry dock

Original Survey, No. 3605 Dated _____ Classed 10 A1

Port Liverpool

REPAIRS

At the present time Caulked from Keel to gunwale
 Coppered to the wales on Paper -

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Copstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Planking	Wales	Masts, Yards, &c. <u>Good</u>
Rank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Sufficient</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Stitchway Comings	Rudder	Anchors No. of
Keelhooks	Copper	Standing & Running Rigging

General Observations and Opinion,

The vessel is in very good condition for the
 safe conveyance of dry stowable goods to & from all parts
 of the world, and in my opinion should remain as, before

Wm. J. Black

The Amount of Fee.....£ : 10 : is received by me, *Wm. J. Black*

Committee's Minute 23 Jan 1847

Character assigned 10 A1 record

A. B.



© 2019
 Lloyd's Register
 Foundation

LON 616-0356