

10, 363

Original Survey, No. 9419 Port of Louisa Classed 11/1

Decks	Good	Transoms	Good	Capstan	
Upper Deck Beams & Fastenings	Firm	Timbers of the Frame	No Shrinkage	Pumps	efficient
Lower Deck Beams & Fastenings	No	Topsides	Good	Masts, Yards, &c.	do
Decking	Good	Wales	No	Sails	No
Blank Shears	No	Counter	No	Cables	No
Waterways	No	Plank and Treenails	No	Anchors	No. of No
Hatchway Comings	No	(Outside to the Water's Edge.)		Standing & Running Rigging	No
Breasthooks	No	Rudder	No	Copper	Good
		Windlass	No		

General Observations and Opinion,
as required by the Instructions, She is in a very efficient condition fit for
the service of any and perishable Cargos to and from
all parts of the world and may remain as classed

Character assigned LX / 1 Petersen

Original Survey, No. 34 Port of Gills Classed 10 *B. 1

Decks	Good	Transoms	Good	Capstan	
Upper Deck Beams & Fastenings	Firm	Timbers of the Frame	good when seen	Pumps	efficient
Lower Deck Beams & Fastenings	do	Topsides	Good	Masts, Yards, &c	do
Spirketting	Good	Wales	do	Sails	do
Plank Shears	do	Counter	do	Cables	do
Waterways	do	Plank and Treenails	do	Anchors No. of	do
Hatchway Comings	do	(Outside to the Water's Edge.)		Standing & Running Rigging	do
Breasthooks	do	Rudder	do	Copper	Good
		Windlass	do		

General Observations and Opinion,
as required by the Instructions, *two new Stations and Waterways to Caalicut*
Is in an efficient Condition for the conveyance of men
and perishable Cargos to and from all parts of the World

Character assigned 1st Lt. 1st Regt.