

ANNUAL SURVEYS.

10.364

No. 11 Survey held at London Date Jan^y 20 1844
 on the By General Wolfe Master Ward
 Tonnage 200 Built at Greenock When built 1825
 By whom built Anderson Owners Anderson
 Port belonging to Glasgow Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 9699 Port of London Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>very fair condition</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>sound & secure</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>1</u>	Topsides <u>very fair condition</u>	Masts, Yards, &c. <u>1</u>
Spirketting <u>good</u>	Wales <u>1</u>	Sails <u>Well found</u>
Plank Shears <u>1</u>	Counter <u>good</u>	Cables <u>1</u>
Waterways <u>1</u>	Plank and Treenails <u>1</u> (Outside to the Water's Edge.)	Anchors No. of <u>1</u>
Hatchway Comings <u>1</u>	Rudder <u>1</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>1</u>	Windlass <u>1</u>	Copper <u>patched</u>

General Observations and Opinion, Three after lengths of the sides shifted in the Starboard
side, caulked from the keel to the gunwale & treenails examined
every beam at her fastenings and I am of opinion is fit
for the safe conveyance of dry & perishable cargoes &
may continue as classed

Committee Minute 26th January 1844

Character assigned A.1

No. 12 Survey held at London Date January 20 1844
 on the Bk Dale Park Master S. Smith
 Tonnage 402 Built at London When built 1820
 By whom built Hawkes Owners Davidson & Co
 Port belonging to London Destined Voyage Port Philip
 If Surveyed Afloat or in Dry Dock Smackeln ship

Original Survey, No. 9246 Port of London Classed 12. A.1
Cont 40 - 4

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>1</u>	Timbers of the Frame <u>sound & secure</u>	Pumps <u>1</u>
Lower Deck Beams & Fastenings <u>1</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>1</u>
Spirketting <u>Good</u>	Wales <u>1</u>	Sails <u>Well found</u>
Plank Shears <u>1</u>	Counter <u>1</u>	Cables <u>1</u>
Waterways <u>1</u>	Plank and Treenails <u>1</u> (Outside to the Water's Edge.)	Anchors No. of <u>1</u>
Hatchway Comings <u>1</u>	Rudder <u>1</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>1</u>	Windlass <u>1</u>	Copper <u>Yellow Metal</u>

General Observations and Opinion, At the present time the Forecastle part on, & in new paint both
beam, & bottom hull & stores in a very high state of
efficiency and may retain her present class

Committee Minute 26th January 1844

Character assigned Cont 4. A.1



© 2019

Lloyd's Register Foundation