

ANNUAL SURVEYS.

10,431

No. 86 on the Bg Nelson Survey held at London Date Feb 19 1844
Nov 112 Tonnage 150 Built at Jersey Master Machin
 By whom built _____ Owners Tyser & Co
 Port belonging to London Destined Voyage Switzerland
 If Surveyed Afloat or in Dry Dock Dry Dock Mechan House

Original Survey, No. 8699 Port of London Classed 7 A 1
 Coat 42 1/2

The Surveyor is required to state the present Condition of the

Decks	Transoms <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Sound & secure</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirketting	Wales <u>Good</u>	Sails <u>Well found</u>
Plank Shears	Counter <u>Good</u>	Cables <u>Good</u>
Waterways	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>Good</u>
Hatchway Comings	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
Breasthooks	Windlass <u>Good</u>	Copper <u>Good</u>

General Observations and Opinion, Bottom examined new main piece of rudder & caulked above
 as required by the Instructions, the Copper, and is in a very efficient state to retain her
present character

Committee Minute 23rd February 1844
 Character assigned Coat 2 A 1

Nath. H. P. [Signature]

No. 53 on the Bk Brunette Survey held at London Date Feb 17 & 22 1844
 Tonnage 205 Built at Sunderland Master B Cousins
 By whom built _____ Owners Cousins
 Port belonging to London Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Original Survey, No. 9283 Port of London Classed 7 A 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails <u>Well found</u>
Plank Shears	Counter	Cables
Waterways	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>Good</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>Good</u>
Breasthooks	Windlass	Copper <u>Yellow Metal over paper Feb 1844</u>

General Observations and Opinion, Shipped, bottom caulked, and sheathed with yellow
 as required by the Instructions, metal over paper, a pair of staple standards under the
brake beam and the stringers additionally bolted
in good condition to remain as classed

Committee Minute 23rd February 1844
 Character assigned 7 A 1

Nath. H. P. [Signature]