

ANNUAL SURVEYS.

10, 497

No. 125 Survey held at London Date March 19th 1844
 on the Bk George Tyne Master Pike
 Tonnage 391 Built at Beith When built 1839
 By whom built _____ Owners Tyne & Co
 Port belonging to Dundee Destined Voyage Cabotage
 If Surveyed Afloat or in Dry Dock West India Dock

Last Original Survey, No. 8799 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & unsees</u>	Pumps
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c.
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails
Plank Shears <u>"</u>	Counter <u>"</u>	Cables
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings <u>Good</u>	Rudder <u>"</u>	Standing & Running Rigging
Breasthooks <u>"</u>	Windlass <u>"</u>	<u>Yellow Metal 1042</u>

General Observations and Opinion, Has been in dry dock & had her bottom examined,
 as required by the Instructions, and is in a very efficient state to retain her
present Class

Committee Minute 22nd March 1844

Character assigned 12A1

Auth. W. Wilson

No. 502 Survey held at London Date March 10th 1844
 on the Bk John Pirie Master Monice
 Tonnage 279 Built at Sunderland When built 1820
 By whom built _____ Owners Parker & Co
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Original Survey, No. 9051 Port of London Classed A, 1st class

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & unsees</u>	Pumps
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c.
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper

General Observations and Opinion, Bottom examined & the Masts and upper works caulked,
 as required by the Instructions, from her general good appearance I am of opinion she is fit
for the safe conveyance of dry & perishable cargoes to
and from all parts of the World and may continue as before
A, 1st class

Committee Minute 22nd March 1844

Character assigned A, 1st class



Lloyd's Register
Foundation