

# ANNUAL SURVEYS.

10,508

No. 18 Survey held at London Date March 22 1844  
 on the Bk Underwood Master Buffett  
 Tonnage 315 Built at Shewich When built 1810  
 By whom built \_\_\_\_\_ Owners Biddings  
 Port belonging to London Destined Voyage St Kitts  
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 9942 Port of London

Classed E1 Notwick

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Stand</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good &amp; firm</u>	Timbers of the Frame <u>sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>good</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well frayed</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Galleys taken off & upper works caulked, she is in a very  
 as required by the Instructions, good & efficient state, & fit for the safe conveyance of Dry  
& perishable cargoes to & from all parts of the World  
and may continue in her present class E1 Notwick

Committee Minute 26th March 1844

Character assigned E1 Notwick

No. 573 Survey held at London Date March 22 1844  
 on the Bk Cleopatra Master Prothwell  
 Tonnage 331 Built at Sunderland When built 1837  
 By whom built \_\_\_\_\_ Owners Cochran & Co  
 Port belonging to London Destined Voyage Demerara  
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. 9026 Port of London

Classed IIA1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame <u>sound where seen</u>	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Good</u>
Waterways	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, Is throughout in a very good and efficient state to  
 as required by the Instructions, retain her present class

Committee Minute 26th March 1844

Character assigned IIA1



© 2019

Lloyd's Register  
Foundation