

ANNUAL SURVEYS.

10,509

No. 361 Survey held at London Date 15 April 1844
 on the Brig Alexander Master William
 Tonnage 207 Built at Berdeen When built 1840
 By whom built 211 Owners Leslie
 Port belonging to Berdeen Destined Voyage Cape of Good Hope
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1030 Port of Berdeen Classed 9 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good Caulked</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>Good</u>	Rudder <u>do</u>	Copper <u>1840 - Good</u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions, Bulwarks & Stanchions repaired upper works waterways
& Caulked She is in an efficient condition and may remain as classed

Committee Minute 19th April 1844

Character assigned 9 A1

Special Damage without report £1.1

No. 38 Survey held at London Date 15 April 1844
 on the By James Master James
 Tonnage 134 Built at Bermuda When built 1840
 By whom built 184 Owners Gilbert
 Port belonging to Bermuda Destined Voyage Bermuda
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10083 Port of London Classed 8 A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u>Good</u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions, She appears in good condition and may remain
as classed -

Committee Minute 19th April 1844

Character assigned 8 A1



© 2019

Lloyd's Register
Foundation