

ANNUAL SURVEYS.

Rec'd 13 May

10. 1834

No. 12 Survey held at London Date May 10th 1844
 on the Bk Caleb Angas Master Whittle 27
 Tonnage 304 Built at Shilds When built 1829
 By whom built _____ Owners C & J Angas
 Port belonging to London Destined Voyage Honduras
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 9479 Port of London

Classed 10 A. 1
 Coult. 40 3

The Surveyor is required to state the present Condition of the

Decks <u>in condition</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>sound & otherwise</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>good</u>
Spirketting <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>in condition</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>Good</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Yellow Metal</u>

General Observations and Opinion, At the present time on the Brake Deck from the Main rigging
 as required by the Instructions, after new plank shears, shear stake & waterway, the timbers
where exposed very sound & I am of opinion to fit for the safe
conveyance of dry & perishable cargoes and may be

Committee Minute 14th May 1844

Character assigned A. 1

No. 57 Survey held at London Date May 1844
 on the Ship Camilla Master Canney
 Tonnage 303 Built at Newcastle When built 1829
 By whom built _____ Owners Burton & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Flitchers Dock

Last Survey, No. 9909 Port of London

Classed 12 A. 1
 Coult. 41 4

The Surveyor is required to state the present Condition of the

Decks _____	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>sound & otherwise</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings _____	Topsides <u>Good</u>	Masts, Yards, &c. <u>good</u>
Spirketting _____	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>Good</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways _____	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings _____	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks _____	Windlass <u>"</u>	Copper <u>in 1843</u>

General Observations and Opinion Head & cutwater taken down & refitted & partially caulked
 as required by the Instructions, and from her general good appearance may retain her
her present character

Committee Minute 14th May 1844

Character assigned and?



© 2019

Lloyd's Register
Foundation