

REPORT of SURVEY for REPAIRS.

Change of property

10.665

Rec'd 22 March

No. 782 Survey held at London Date May 15th 1844
 on the Bⁿ Ethelred Master W B Bedford
 Tonnage 421 Per Register Built at London When built 1811
 By whom built Pellissier Owners Hamilton
 Port belonging to London Destined Voyage Provia Schetoc & Gunn's Island
 If Surveyed Afloat or in Dry Dock Dowson's Slip

Last Survey, No. 9490 Feb^y 1843 Classed A.1
 Port London

REPAIRS

Two Hundred sheets of Copper put on

P. H. d. & C. 37

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettig	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, She is in an efficient state for the conveyance of dry and perishable cargoes to and from all parts of the world and in my opinion eligible to remain as classed A.1

George Bayley

The Amount of Fee.....£ 2 : : is received by me, H. M. M. M.

Committee's Minute 24th May 1844

Character assigned A.1 estimated

G. D. H.



© 2019

Lloyd's Register Foundation

LON 617-0192