

ANNUAL SURVEYS.

10,698

Rec^d 25 May

No. 290 Survey held at London Date 20th May 1844
 on the John Ship Master Thompson
 Tonnage 189 Built at P. & S. Lane When built 1841
 By whom built Owners McDonald
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1889 Port of Newcastle Classed 4 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>do when seen</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u> </u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions, Is in good efficient condition and may remain as Classed

Committee Minute 20th May 1844

Character assigned 4 A 1

No. 347 Survey held at London Date May 17 1844
 on the Countess of Durham Master Cobden
 Tonnage 257 Built at Sunderland When built 1840
 By whom built 264 Owners Robinson
 Port belonging to London Destined Voyage Constantinople
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 5372 Port of Liverpool Classed 9 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame <u>do when seen</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u>Good</u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions, She appears in good and efficient condition and may remain as Classed

Committee Minute 20th May 1844

Character assigned 9 A 1



© 2019

Lloyd's Register Foundation