

# ANNUAL SURVEYS.

10.773

No. 125 Survey held at London Date June 184 4  
 on the "Mermaid" Master Martin  
 Tonnage 159 Built at Garmouth When built 1827  
 By whom built — Owners Lay & Co  
 Port belonging to Garmouth Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9847 Port of London

Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>the same</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>Caulked</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u>Good</u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions, Is in good Condition for the conveyance of dry and perishable Cargoes to & from all parts of the World and may remain as Classed

Committee Minute 25th June 184 4

Character assigned A.1

No. 156 Survey held at London Date 11 June 184 4  
 on the "Anne" Master Seager  
 Tonnage 117 Built at Little Hampton When built 1834  
 By whom built 179 Owners Lyon  
 Port belonging to Foote Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1156 Port of Liverpool

Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u>Good</u>
	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions, Is in an efficient Condition and may remain as Classed

Committee Minute 25th June 184 4

Character assigned A.1



© 2019

Lloyd's Register Foundation