

ANNUAL SURVEYS.

10.818

Recd 5 July

No. 237 Survey held at London Date 25 June 1844
 on the Park Black River Packet Master Baker
 Tonnage 265 Built at Burhampton When built 1825
 By whom built Owners Captain & Co X
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock in Blackwood Dock

Last Survey, No. 10332 Port of London Classed 10 A 1
1845 Rest 7 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u> </u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Topsides <u> </u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u> </u>	Wales <u> </u>	Sails <u> </u>
Plank Shears <u> </u>	Counter <u> </u>	Cables <u> </u>
Waterways <u> </u>	Plank and Treenails <u> </u>	Anchors No. of <u>30 10 11</u>
Hatchway Comings <u> </u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>Good</u>
Breasthooks <u> </u>	Rudder <u> </u>	Copper <u>Good</u>
	Windlass <u> </u>	

General Observations and Opinion,

as required by the Instructions, at present the Caulking of Water Toppides has
been overhauled - a New Mizen Mast furnished
to the Ship she is in very efficient condition

Committee Minute 9th July 1844
 Character assigned Rest 7 A 1 and May remain as Classed
Joseph H. Hatcher

No. 257 Survey held at London Date 29 June 1844
 on the Brig "Urethusa" Master McMurdy
 Tonnage 200 Built at Whitby When built 1823
 By whom built Owners Mutiny
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock in Fore & aft Dock

Last Survey, No. 8855 Port of London Classed R. 1

The Surveyor is required to state the present Condition of the

Decks <u>firm</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u>Not seen</u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Topsides <u> </u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u> </u>	Wales <u> </u>	Sails <u> </u>
Plank Shears <u> </u>	Counter <u> </u>	Cables <u> </u>
Waterways <u> </u>	Plank and Treenails <u> </u>	Anchors No. of <u>30 10 11</u>
Hatchway Comings <u> </u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>Supp</u>
Breasthooks <u> </u>	Rudder <u>Good</u>	<u>4 Metal on file</u>
	Windlass <u> </u>	<u>New Crane 1844</u>

General Observations and Opinion,

as required by the Instructions, at present the bottom has been stripped Caulked
fitted and resheathed with Yellow Metal
the topsides have also been Caulked - she appears
fit for the safe conveyance of dry

Committee Minute 9th July 1844
 Character assigned Rest 7 A 1 and May remain as Classed
revised 9th July 1844
W. H. Hatcher