

ANNUAL SURVEYS.

10840

Recd 18th July

No. 291 Survey held at London Date July 13. 16 184 4
 on the "Atlas" Master Atkins
 Tonnage 412 Built at London When built 1820
 By whom built — Owners Chalmers & Co
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9429 Port of London Classed F. 1
 Rest. 35-6 Jrs Coult at 2 Jrs

Surveyor is required to state the present Condition of the

Deck Beams & Fastenings <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Efficient</u>
Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>Much exposed</u>	Pumps <u>do</u>
Deck Beams & Fastenings <u>do</u>	Topsides <u>are good</u>	Masts, Yards, &c. <u>do</u>
Deck Beams & Fastenings <u>do</u>	Wales <u>do</u>	Sails <u>do</u>
Deck Beams & Fastenings <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Deck Beams & Fastenings <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Deck Beams & Fastenings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Deck Beams & Fastenings <u>do</u>	Rudder <u>do</u>	Copper <u>Good</u>
Deck Beams & Fastenings <u>do</u>	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions,

Now Caulked from the copper up new steps
Main Mast is in an efficient condition for for the conveyance
dry and perishable Cargos to & from all parts of the world

Committee Minute 19th July 184 4 and may be Classed F. 1 at least
 Character assigned F. 1 Antelope Houtman

No. 37 Survey held at London Date July 17 184 4
 on the "Regia" Master Spencer
 Tonnage 128 Built at Garnmouth When built 1839
 By whom built — Owners Silva & Son
 Port belonging to London Destined Voyage Roumaysberg
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9875 Port of London Classed G. 1

Surveyor is required to state the present Condition of the

Deck Beams & Fastenings <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Efficient</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>do</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Deck Beams & Fastenings <u>do</u>	Wales <u>do</u>	Sails <u>do</u>
Deck Beams & Fastenings <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Deck Beams & Fastenings <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Deck Beams & Fastenings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>do</u>
Deck Beams & Fastenings <u>do</u>	Rudder <u>do</u>	Copper <u>—</u>
Deck Beams & Fastenings <u>do</u>	Windlass <u>do</u>	

General Observations and Opinion,

as required by the Instructions,

General appearance good Sound may in my
opinion remain as Classed

Committee Minute 19th July 184 4

Character assigned G. 1



© 2019

Lloyd's Register
Foundation