

# ANNUAL SURVEYS.

10869  
Recd 29 July

No. 578 Survey held at London Date July 17 to 20 1844  
on the Bk Mary Gay Master A. W. Wain  
Tonnage 225 Built at Peterhead When built 1837  
By whom built \_\_\_\_\_ Owners Wain & Co  
Port belonging to London Destined Voyage Lancaster  
If Surveyed Afloat or in Dry Dock Bullhead Dock

Last Survey, No. 9783 Port of London Classed 9A1

The Surveyor is required to state the present Condition of the

|                               |  |                            |
|-------------------------------|--|----------------------------|
| Decks                         | Transoms   | Capstan                    |
| Upper Deck Beams & Fastenings | Timbers of the Frame                                 | Pumps                      |
| Lower Deck Beams & Fastenings | Topsides   | Masts, Yards, &c.          |
| Spirkettling                  | Wales  | Sails                      |
| Plank Shears                  | Counter  | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge) | Anchors No. of             |
| Hatchway Comings              | Rudder   | Standing & Running Rigging |
| Breasthooks                   | Windlass   | Copper                     |

*Good* *Good* *Good* *sufficient*

General Observations and Opinion, Bottom caulked and sheathed with yellow metal  
as required by the Instructions, over paper and appears in all respects eligible to retain  
her present class

Committee Minute 30th July 1844

Character assigned 9A1 *recd Gm*

*L.R.*

No. 928 Survey held at London Date July 19 to 24 1844  
on the Sr Miranda Master W. H. Wain  
Tonnage 131 Built at Cowes When built 1838  
By whom built White Owners Baylis  
Port belonging to London Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock Fountain Dock

Last Survey, No. 9922 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

|                               |  |                            |
|-------------------------------|--|----------------------------|
| Decks                         | Transoms   | Capstan                    |
| Upper Deck Beams & Fastenings | Timbers of the Frame                                 | Pumps                      |
| Lower Deck Beams & Fastenings | Topsides   | Masts, Yards, &c.          |
| Spirkettling                  | Wales  | Sails                      |
| Plank Shears                  | Counter  | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge) | Anchors No. of             |
| Hatchway Comings              | Rudder   | Standing & Running Rigging |
| Breasthooks                   | Windlass   | Copper                     |

*Good* *Good* *Not found*

General Observations and Opinion, Upper patches about 100 sheets round the bows  
as required by the Instructions, is in a very efficient state to retain her present  
class

Committee Minute 30th July 1844

Character assigned 12A1 *L.R.*



© 2019  
Lloyd's Register  
Foundation  
LON 617-0409