

ANNUAL SURVEYS.

To raise Claps

10899

Rec'd by

No. 468 Survey held at London Date August 4 1844
 on the Bk Mary Master William By
 Tonnage 116 Built at Sunderland When built 1820
 By whom built Markham Owners Markham
 Port belonging to Stockton Destined Voyage Stockton
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 442 Port of Stockton Classed E, 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>Withstand</u>
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging <u>Good</u>
Breasthooks	Windlass	

General Observations and Opinion, *for repairs see Stockton survey dated June last, from the large*
 as required by the Instructions, *repairs and her general good & efficient condition as far as can,*
be seen I am of opinion she is fit for the safe conveyance
of perishable cargoes to & from all parts of the North
and may be raised to E. & 1
 Committee Minute 9 August 1844
 Character assigned E. & 1 *Stewart*

No. 187 Survey held at London Date August 1844
 on the Bk Niagara Master Champion
 Tonnage 390 Built at Sunderland When built 1836
 By whom built Greenwell Owners Greenwell
 Port belonging to Sunderland Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 2316 Port of Sunderland Continued 1843 Classed Two Years A1

The Surveyor is required to state the present Condition of the

Decks	Transoms <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Sound & where necessary</u>	Pumps
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Masts, Yards, &c.
Spirkettling	Wales	Sails <u>Good</u>
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>sufficient</u>
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	<u>Yellow Metal over paper</u>

General Observations and Opinion, *Shipped, bottom caulked, and sheathed with Yellow Metal*
 as required by the Instructions, *over paper, & appears in good condition to receive her present*
Claps

Committee Minute 9 August 1844
 Character assigned E. & 2 *Stewart*



© 2019

Lloyd's Register
Foundation