

ANNUAL SURVEYS.

11058

Rec^d 12 Oct

No. 25 Survey held at London Duplicate Date Oct 2 1844
 on the Bk Caledonia Master Liddell
 Tonnage 445 Built at Newcastle When built 1836
 By whom built _____ Owners Mr Fairlane
 Port belonging to Alcoa Destined Voyage New South Wales
 If Surveyed Afloat or in Dry Dock At the Dock

Last Survey, No. _____ Port of London Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Yellow Metal over felt</u>

General Observations and Opinion, Bottom & topsides caulked and sheathed with yellow
 as required by the Instructions, Metal over felt and appears in a good & efficient state
to retain her present shape

Committee Minute _____ 184

Character assigned _____

[Signature]

No. 53 Survey held at London Date Oct 587 1844
 on the Bg Davidson Master Cannings
 Tonnage 205 Built at Perth When built 1842
 By whom built _____ Owners Shills
 Port belonging to Perth Destined Voyage Constantinople
 If Surveyed Afloat or in Dry Dock in the Ways

Last Survey, No. 693 Port of Dundee Classed 5 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound where seen</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Copper patched and is in other respects in good condition
 as required by the Instructions, to retain her present character

Committee Minute 15th Oct 1844

Character assigned 5 A 1

[Signature]



© 2019

Lloyd's Register
Foundation

LONG 618-0069