

No. <sup>84</sup>

on the

Survey held at London

Date

August 5<sup>th</sup>1844

11063

Tonnage 122Built at RyeWhen built 1826

By whom built

Owners

ButtschildPort belonging to London

Destined Voyage

Seville

If Surveyed Afloat or in Dry Dock

Gibbons WaysOriginal Survey, No. 8856

Port of

LondonSince 1843

Classed

F. 1

The Surveyor is required to state the present Condition of the

Decks

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Spirketting

Plank Shears

Waterways

Hatchway Comings

Breasthooks

Transoms

Timbers of the Frame

Topsides

Wales

Counter

Plank and Treenails

(Outside to the Water's Edge.)

Rudder

Windlass

Capstan

Pumps

Masts, Yards, &amp;c.

Sails

Cables

Anchors No. of

Standing &amp; Running Rigging

Copper single

General Observations and Opinion,

as required by the Instructions,

Caulked from keel up. the bottom firm and good.  
Rigging & sails good and efficient, in my opinion she  
is eligible to remain as classed F. 1

Committee Minute

18<sup>th</sup> Oct1844

Character assigned

F. 1George Bayley

© 2019

Lloyd's Register  
Foundation