

REPORT of SURVEY for REPAIRS.

11065

Change of Owners

Re: 24/11

No. 666 Survey held at London Date August 30th 1844
 on the Bk Commodore Master Pasmore
 Tonnage 203 Built at Newport When built 1835
 By whom built _____ Owners J. Shepherd & Co No change
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 9882 Classed 12A1

Port of London
 REPAIRS Caulked in 1843

Present Condition of the

Decks	Transoms <u>Stand</u>	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame <u>stand where seen</u>	Capstan
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Pumps
Spirketting	Wales <u>"</u>	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter <u>"</u>	Sails <u>Sufficient</u>
Waterways	Plank & Treenails (Outside to the Water's Edge) <u>Good</u>	Cables
Hatchway Comings	Rudder <u>"</u>	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Presents a very firm appearance and appears in all respects in good condition to retain her present class

[Signature]

The Amount of Fee £ is received by me,

Committee's Minute 18th Oct 1844

Character assigned 12A1

[Signature]



© 2019

Lloyd's Register
 Foundation
 LON 618-0077