

ANNUAL SURVEYS.

11106

No. 356 Survey held at London Date 30 Oct 1844
 on the Duke of Manchester Master Murry
 Tonnage 369 Built at London When built 1819
 By whom built London Owners Hibberts
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 10142 Port of LondonClassed A:1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>Efficient</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,
as required by the Instructions,

Her fastenings are secure and she appears
in good and efficient condition fit for the conveyance
of dry and perishable cargoes to & from all parts of the

Committee Minute 1st Nov. 1844

Character assigned A:1 Fit for service and may remain as
Classed

No. 608 Survey held at London Date 30 Oct 1844
 on the St. Saviour Master Baillie
 Tonnage 276 Built at Bermuda When built 1832
 By whom built London Owners Sutherland
 Port belonging to Vincent Destined Voyage Vincent
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 9455 Port of LondonClassed A:1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>do</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>Now Caulked</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>Good</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>Good</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,
as required by the Instructions,

Is throughout in good condition fit for
the conveyance of dry and perishable cargoes to & from
all parts of the world and may remain as Classed

Committee Minute 1st Nov. 1844

Character assigned A:1 Fit for service

Lloyd's Register
Foundation