

ANNUAL SURVEYS.

11124

No. 121 Survey held at London Date 29 October 1844
 on the By Anne Master Blackindoe
 Tonnage 192 Built at Port Glasgow When built 1819
 By whom built Owners Louther
 Port belonging to London Destined Voyage to Kitts
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 10059 Port of London

Classed HA1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u>Seem</u>	Timbers of the Frame <u>do show Sun</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions, She is in good & efficient condition fit for the conveyance of dry & perishable cargo, and from all parts of the world and may run as a coaster.

Committee Minute 8th Nov 1844

Character assigned HA1 Antigua

No. 35 Survey held at London Date October 1844
 on the Mc Barbara Master Relohie
 Tonnage 338 Built at Swansea When built 1836
 By whom built Owners Coroon
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 9919 Port of London

Classed HA1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u>Seem</u>	Timbers of the Frame <u>do show Sun</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions, Is in good & efficient condition and may run as a coaster — has been surveyed several times 1843 and the reports not acted upon

Committee Minute 8th Nov 1844

Character assigned HA1



© 2019

Lloyd's Register Foundation