

# REPORT of SURVEY for REPAIRS.

Charge of Owners

No. 28 Survey held at London Date 26<sup>th</sup> Nov 1844

on the S<sup>r</sup> Nancy Master J. H. Laws

Tonnage 93 Built at Leith When built 1838

By whom built Owners J. H. Laws

Port belonging to London Destined Voyage Cape of Good Hope

If Surveyed Afloat or in Dry Dock on West & Smiths Quay

Last Survey, No. 10781 Classed O A 1

Port Hull London

REPAIRS This vessel is partly iron fastened which are covered over with cement & lead, bottom caulked and sheathed with yellow metal over paper.

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails	Cables
Hatchway Comings	(Outside to the Water's Edge)	Anchors
Breasthooks	Rudder	No. of
	Copper yellow metal over paper	Standing & Running Rigging

General Observations and Opinion. From her good & efficient condition I am of opinion she may continue in her present shape.

The Amount of Fee £ 10 : is received by me, as per

Committee's Minute 29<sup>th</sup> Nov 1844

Character assigned S A 1



© 2019 Lloyd's Register Foundation LON 618 - 0181