

ANNUAL SURVEYS.

11169
Recd 28 Nov
H

No. 271 on the *Bk* Survey held at *London* Date *Nov 23, 26 & 27* 1844
Master *M Simpson*
Tonnage *280* Built at *Whitby* When built *1836*
By whom built _____ Owners *Demonds & Co*
Port belonging to *London* Destined Voyage *Naples*
If Surveyed Afloat or in Dry Dock *Gun Dock*

Last Survey, No. *10088* Port of *London* Classed *10A1*

The Surveyor is required to state the present Condition of the

| | | |
|--|---|--|
| Decks <i>Good</i> | Transoms <i>Sound</i> | Capstan <i>Good</i> |
| Upper Deck Beams & Fastenings <i>"</i> | Timbers of the Frame <i>Sound where seen</i> | Pumps <i>"</i> |
| Lower Deck Beams & Fastenings <i>"</i> | Topsides <i>Good</i> | Masts, Yards, &c. <i>"</i> |
| Spirkettling <i>"</i> | Wales <i>"</i> | Sails <i>Well found</i> |
| Plank Shears <i>"</i> | Counter <i>"</i> | Cables <i>"</i> |
| Waterways <i>"</i> | Plank and Treenails <i>Good</i> (Outside to the Water's Edge.) | Anchors No. of <i>3 Bows 3 Hedges</i> |
| Hatchway Comings <i>"</i> | Rudder <i>"</i> | Standing & Running Rigging <i>good</i> |
| Breasthooks <i>"</i> | Windlass <i>"</i> | Copper <i>"</i> |

General Observations and Opinion, *Bottom caulked & sheathed with yellow metal over paper*
as required by the Instructions, *and appears in an efficient state to continue as classed*

Committee Minute *29th Nov 1844*

Character assigned *10 A 1* *very good*

W. D. Wilson
Aug. Creech

No. 253 on the *Bk* Survey held at *London* Date *Nov 26* 1844
Master *H Seed*
Tonnage *254* Built at *Sunderland* When built *1832*
By whom built _____ Owners *Sessie Alexander & Co*
Port belonging to *London* Destined Voyage *Carib*
If Surveyed Afloat or in Dry Dock *on the ways*

Last Survey, No. *6008* Port of *Liverpool* Restored 1841 Classed *5A1*

The Surveyor is required to state the present Condition of the

| | | |
|--|---|--|
| Decks <i>Good</i> | Transoms <i>Sound</i> | Capstan <i>Good</i> |
| Upper Deck Beams & Fastenings <i>"</i> | Timbers of the Frame <i>Sound where seen</i> | Pumps <i>"</i> |
| Lower Deck Beams & Fastenings <i>"</i> | Topsides <i>Good</i> | Masts, Yards, &c. <i>"</i> |
| Spirkettling <i>Good</i> | Wales <i>"</i> | Sails <i>Well found</i> |
| Plank Shears <i>"</i> | Counter <i>"</i> | Cables <i>"</i> |
| Waterways <i>"</i> | Plank and Treenails <i>Good</i> (Outside to the Water's Edge.) | Anchors No. of <i>3 Bows 1 Stem 2 Hedges</i> |
| Hatchway Comings <i>"</i> | Rudder <i>"</i> | Standing & Running Rigging <i>good</i> |
| Breasthooks <i>"</i> | Windlass <i>"</i> | Copper <i>patched</i> |

General Observations and Opinion, *Caulked from the Copper to the waterway beam and*
as required by the Instructions, *is in an efficient state to continue in the present*
class

Committee Minute *29th Nov 1844*

Character assigned *Rest 5A1*

W. D. Wilson



© 2019

Lloyd's Register
Foundation