

ANNUAL SURVEYS.

Rec 25 Nov

#1154
11/84

No. Survey held at London Date 17th Dec 20 Nov 1844
 on the Bark "Fairlie" Master J. Roskell
 Tonnage 756 Built at Patentia When built 1812
 By whom built Owners J. Jones
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock in Ship Wigram Dock & East India Dock

Last Survey, No. 9844 Port of LondonClassed *AE 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>Wharfedale</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>—</u>
Spirkettling <u>Caulked</u>	Wales <u>{ Caulked</u>	Sails <u>—</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>—</u>
Waterways <u>—</u>	Plank and Treenails <u>—</u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>—</u>	Rudder <u>New Main Piece</u>	Standing & Running Rigging <u>—</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>Y Metal New Nov 1844</u>

General Observations and Opinion,
as required by the Instructions,

at present stripped, Caulked from Keel to the waterways
 and bottom treenailed with Y Metal New Main Piece of
 Lumber fitted and two pairs new Lumber bands - Knee of Head fastened
 and a pair of iron Chocks fitted all the steering apparatus fitted

Committee Minute

20th Nov 1844

Character assigned

Special L.

and Ship generally overhauled. It is
 in efficient Condition and fit for the safe
 conveyance of dry and perishable cargoes
 to & from all parts of the world & may continue
 as before
 Joseph H. Hatcher

No. Survey held at Date 184
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The Surveyor is required to state the present Condition of the

Decks <u> </u>	Transoms <u> </u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u> </u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Topsides <u> </u>	Masts, Yards, &c. <u> </u>
Spirkettling <u> </u>	Wales <u> </u>	Sails <u> </u>
Plank Shears <u> </u>	Counter <u> </u>	Cables <u> </u>
Waterways <u> </u>	Plank and Treenails <u> </u> (Outside to the Water's Edge.)	Anchors No. of <u> </u>
Hatchway Comings <u> </u>	Rudder <u> </u>	Standing & Running Rigging <u> </u>
Breasthooks <u> </u>	Windlass <u> </u>	Copper <u> </u>

General Observations and Opinion,
as required by the Instructions,Committee Minute 184 Character assigned 

© 2019

Lloyd's Register
Foundation

LON 618-0200