

ANNUAL SURVEYS.

11210

No. 23 Survey held at London Date 20 Nov 1844
 on the "Park" Ganges Master Walker
 Tonnage 417 Built at Calcutta When built 1806
 By whom built _____ Owners Mangles & Pries
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock in the East India Dock

Original Survey, No. _____ Port of _____ Classed *A-1

The Surveyor is required to state the present Condition of the

Decks <u>firm</u>	Transoms <u>where Sea Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>---</u>	Pumps <u>overhauled</u>
Lower Deck Beams & Fastenings <u>---</u>	Topsides <u>---</u>	Masts, Yards, &c. <u>New Mizen Mast & Bowsprit</u>
Spirkettling <u>Caulked</u>	Wales <u>butts Caulked</u>	Sails <u>Sufficient</u>
Plank Shears <u>---</u>	Counter <u>---</u>	Cables <u>---</u>
Waterways <u>---</u>	Plank and Treenails <u>---</u>	Anchors No. of <u>3 B 1st 1 1/2</u>
Hatchway Comings <u>---</u>	Rudder <u>Upper bands refastened</u>	Standing & Running Rigging <u>overhauled</u>
Breasthooks <u>---</u>	Windlass <u>Good</u>	Copper <u>patched Good</u>

General Observations and Opinion,
as required by the Instructions,

*appears fit for the safe conveyance of dry
and perishable Cargoes to & from all parts
of the world and may remain as Classed
6th Dec 1844 *A-1 with alterations J. H. Fletcher*

Committee Minute _____

Character assigned _____

No. 59 Survey held at London Date 2^d Dec 1844
 on the "Venus" Master Mc Donato
 Tonnage 799 Built at Chepstow When built 1838
 By whom built _____ Owners Gibbs & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Original Survey, No. 9667 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>where Sea Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>---</u>	Timbers of the Frame <u>---</u>	Pumps <u>---</u>
Lower Deck Beams & Fastenings <u>the iron bolts renewed of iron</u>	Topsides <u>---</u>	Masts, Yards, &c. <u>---</u>
Spirkettling <u>Good</u>	Wales <u>---</u>	Sails <u>Sufficient</u>
Plank Shears <u>---</u>	Counter <u>---</u>	Cables <u>---</u>
Waterways <u>Caulked</u>	Plank and Treenails <u>---</u>	Anchors No. of <u>3 B 1st 1 1/2</u>
Hatchway Comings <u>---</u>	Rudder <u>---</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>---</u>	Windlass <u>---</u>	Copper <u>---</u>

General Observations and Opinion,
as required by the Instructions,

*at present bottom stripped, Caulked, and Sheathed,
with Yellow Metal on Paper the old iron bolts of the
lower deck knees renewed of iron - She is in very
efficient Condition and may be retained
as Classed*

Committee Minute _____

Character assigned 12 A 1