

ANNUAL SURVEYS.

11215

Rec'd Dec

No. 131 Survey held at London Date 22 29 Nov 1844
 on the M^{rs} "Stratford" Master Saint
 Tonnage 394 Built at London When built 1832
 By whom built White Owners Blyth
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10522 Port of LondonClassed Con. 4A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>"</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

The keel of the Head broken down and shock discovered and stopped caulked and overhauled about the bows is in good condition and may remain as closed

Committee Minute 6th Dec 1844Character assigned Con 4A1

No. 113 Survey held at London Date 25 Nov 1844
 on the M^{rs} Lady Sarah Bayly Master Canny?
 Tonnage 316 Built at New Brunswick When built 1839
 By whom built London Owners Baker & Co.
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10521 Port of LondonClassed 4A1
SS. 44 - 4 Dec 1844

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>do</u>	Pumps <u>Efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion,

as required by the Instructions,

She is in good and efficient condition and may remain as closed

Committee Minute 6th Dec 1844Character assigned 4A1

©2019

Lloyd's Register
Foundation