

REPORT of SURVEY for REPAIRS.

11204

Rec 6 Jan 1845

No. 143 Survey held at London Date Dec 27th Jan 3rd 1845
 on the Bk Caroline Master H Hughes
 Tonnage 372 Built at Shields When built 1832
 By whom built _____ Owners Campbell
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 8402 Continued 1042 Classed 10 Years A1
 Port London

REPAIRS At Lamb's in September 1843. Bottom caulked and Coppered.
at the present time four planks in the deck shifted,
two new lodging oak knees to the hold beams and upper works
caulked.

Present Condition of the

| | | |
|--|--|---|
| Decks <u>Good</u> | Transoms <u>Sound</u> | Windlass <u>Good</u> |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame <u>Sound when seen</u> | Capstan <u>"</u> |
| Lower Deck Beams & Fastenings <u>"</u> | Topsides <u>Good</u> | Pumps <u>"</u> |
| Spirkettling <u>Good</u> | Wales <u>"</u> | Masts, Yards, &c. <u>"</u> |
| Plank Shears <u>"</u> | Counter <u>"</u> | Sails <u>Good</u> |
| Waterways <u>"</u> | Plank and Treenails <u>Good</u> (Outside to the Water's Edge) | Cables <u>"</u> |
| Hatchway Comings <u>"</u> | Rudder <u>"</u> | Anchors No. of <u>3 Bower 1 Stm 2 Kedge</u> |
| Breasthooks <u>"</u> | Copper <u>"</u> | Standing & Running Rigging <u>"</u> |

General Observations and Opinion, In a very good condition and appears in an efficient
state both in the hull & stores to retain her
present character.

[Signature]

The Amount of Fee.....£ : : is received by me,

Committee's Minute 7th Jan 1845

Character assigned Capt 3 A



© 2019

Lloyd's Register
Foundation

LONG18-0280