

REPORT of SURVEY for REPAIRS. 11268

No. 884 Survey held at London Date Dec 5, 6, 17, 28 ¹⁸⁴⁴ Jan 1 1845
 on the Sh. Wallow Master Mittler
 Tonnage 116 Built at Gibraltar When built 1824
 By whom built — Owners Walker
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Dry dock & Afloat

Last Survey, No. 884.9 Classified A.1

Port London

REPAIRS Dec^r 1844, Jan^r 1845 - At the suggestion of Surveyor

About 40 new top timbers & Ruff her timbers part new Sheer Strakes
 greater part new plank sheers, part new waterways Decks doubled
 with 1 1/2 inch plank upon felt, several new planks in each
 bow part new turnvoiled and many new bolts through plank
 and new timbers Caulked from the Copper up from the Copper
 to the Comings new bolts in the beam ends & Shelf

1844 Shipped bottom caulked and sheathed with yellow painted

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

She is now in a good & efficient condition for the carriage
 of dry & perishable Cargos and may remain as ordered

The Amount of Fee.....£ : 10 : is received by me, Wm. H. Ritchie

Certificate (if required) : 5 : —

Committee's Minute 7 Jan 1845

Character assigned A.1



© 2019

Lloyd's Register
Foundation

LONGB-0284

Special to pump out condition £2 2
 Superintend repairs