

ANNUAL SURVEYS.

11299

No. 103 Survey held at London Date Jan 14th 1845
 on the SS Barrow Master T. Seggell
 Tonnage 103 Built at Yarmouth When built 1839
 By whom built Withams Owners Withams
 Port belonging to London Destined Voyage Trinidad
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 1025 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirketting	Wales	Sails <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>sufficient</u>
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper <u>1843</u>

General Observations and Opinion, Caulked in 1844 and is in all respects in a very good and
 as required by the Instructions, efficient state to retain her present shape

[Signature]

Committee Minute 21st Jan 1845

Character assigned 12 A 1

No. 168 Survey held at London Date January 15th 1845
 on the Bk Carrara Master R. Miller
 Tonnage 210 Built at Simskilms When built 1839
 By whom built Seath Owners Thompson
 Port belonging to Seath Destined Voyage Genoa & Mauritius
 If Surveyed Afloat or in Dry Dock Gun Dock

Last Survey, No. 1026 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound & strong</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Wales <u>"</u>	Sails <u>Well found</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails (Outside to the Water's Edge.) <u>"</u>	Anchors No. of <u>3 Bows & Stem & Rudge</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Y.M.</u>

General Observations and Opinion, Copper stripped off, bottom caulked and sheathed with
 as required by the Instructions, yellow metal over paper, and appears in all respects
in an efficient state to retain her present shape

Committee Minute 21st Jan 1845

Character assigned 12 A 1